HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Nathaniel Crosby III House 703 Deschutes Way Tumwater Thurston County Washington HABS No. WA-162

Ed Hildreth,	Photographer	July 1984
--------------	--------------	-----------

- WA-162-2 EAST FRONT
- WA-162-3 KITCHEN ADDITION, EAST PORCH
- WA-162-4 GENERAL VIEW LOOKING SOUTHEAST
- . WA-162-5 REAR, KITCHEN WING AND ADDITION
 - WA-162-6 KITCHEN WING, SOUTH PORCH
 - WA-162-7 FRONT (EAST) DOOR DETAIL
 - WA-162-8 SOUTH DOOR DETAIL
 - WA-162-9 FIRST FLOOR, PARLOR, EAST WALL
 - WA-162-10 FIRST FLOOR, PARLOR, WEST WALL, FIREPLACE DETAIL
 - WA-162-11 FIRST FLOOR, SITTING ROOM LOOKING THROUGH DOUBLE DOOR TO DINING ROOM
 - WA-162-12 FIRST FLOOR, ENTRANCE HALL, STAIRCASE
 - WA-162-13 SECOND FLOOR, NORTHEAST BEDROOM
 - WA-162-14 SECOND FLOOR, SOUTHWEST BEDROOM